


Input common end	stand-by	Powder recovery	Phase sequence errors	Feed motor overload	Vacuum pump overload	Drive overload	Bin sensor
------------------	----------	-----------------	-----------------------	---------------------	----------------------	----------------	------------

Door signal	Capsule sensor	scram	Vacuum cleaner overloaded	Positioning sensor	Click box (optional)
-------------	----------------	-------	---------------------------	--------------------	----------------------


stand-by

PLC Power supply



1X/=PLT-163R+P
2X/=PLT-163R+P
3X/=PLT-163AD+P

Note: the input of PLC is yellow 0.5mm²

 www.lfamachines.com	Drawing Name	FACF-1200 Wiring 5
	Product Name	FACF-1200
	Version	v1.0
	Provided By	LFA Machines