

Components list

No.	Symbol	Description	Model	No.	Symbol	Description	Model	No.	Symbol	Description	Model
1	CPUST40	PLC	6ES72881ST400AA0	14	KM1	contactor	3RT6026-1AN20				
2	VF	VFD	ACS355-03E-07A5-2	15	KM2	contactor	3RT6016-1AN21				
3	HMI	Siemens touch screen	6AV6648-0CC11-3AX0	16	KM3	contactor	3RT6026-1AN20				
4	QS1	Power switch	P1-32	17	U	Dc power supply	LRS-50-24				
5	QF1	air switch	5SL62047CC	18	KVS	Phase sequence protector	3UG4512-1AR20				
6	QF2	air switch	5SL63167CC	19	K	weidmueller relay	DR424024LD/SDI2COECO				
7	QF3	switch	3RV6011-1KA10	20	X0	weidmueller terminal	ZDU1.5/ZDU2.5/ZDU6				
8	QF4	switch	3RV6011-1CA10	21	H1	buzzer	HRB-PS30-DC24V				
9	QF5	switch	3RV6011-1KA10	22	XS1	Dry pump socket	5623				
10	QF6	air switch	5SL62167CC	23	XS2	Vacuum socket	5618				
11	QF7	air switch	5SL62047CC	24	XS3	Capsule hoist source	5601				
12	QF8	air switch	5SL62167CC	25	XS4	Polished electromechanical source	5601				
13	KM0	contactor	3RT6027-1AN20								



www.lfamachines.com

Drawing Name	FACF-1200 Wiring 14
Product Name	FACF-1200
Version	v1.0
Provided By	LFA Machines