



L1 L2 L3 N PE U1 V1 W1 U2 V2 W2 U3 V3 W3 U4 V4 W4

L21 A1 Q5 +V +V +V -V -V -V I0 I1 I5 I6 I7

Fully automatic capsule filling machine



www.lfamachines.com

Drawing Name	FACF 1200 Wiring Diagram 17
Product Name	FACF 1200
Version	V1.0
Provided By	LFA Machines